Application No.: 09/380,614 Examiner: N. W. Woodall

Art Unit: 3733

REMARKS

Reconsideration of the pending application is respectfully requested on the basis of

the following particulars:

.

In the claims

Claim 1 is amended to more clearly describe the present invention. Claim 1 is

amended to clarify that the plate is mounted completely within an open cylindrical inner

part of the nut. Support for this amendment is found at line 21 of page 2, line 15 of page

4, and Figs. 2 and 3.

Claim 1 is also amended to clarify that the two lateral clearances are configured

and dimensioned to receive the two pins of the auxiliary tool when the lateral branches of

the fixing head are engaged in the lateral clearances.

Rejection of claim 1 under 35 U.S.C. § 103(a)

Claim 1 presently stands rejected as being unpatentable over Byrd (U.S. 5,466,237)

in view of Blackburn (U.S. 2,108,957). This rejection is respectfully traversed for at least

the following reasons.

It is respectfully submitted that Byrd and Blackburn, either individually or in any

combination, fail to disclose or suggest all of the elements of claim 1.

In particular, these references fail to disclose or suggest a nut comprising a plate

mounted completely within an open cylindrical inner part of the nut, the plate being in free

rotation in and extending diametrically across the open cylindrical inner part.

The examiner recognizes that "Byrd fails to disclose the device wherein the

threaded nut further includes a plate mounted in free rotation in the bore of the threaded

nut wherein the width of the plate defines two lateral clearances capable of allowing the

branches of a fixture [to] pass through." (page 2 of the Office action).

4

Application No.: 09/380,614 Examiner: N. W. Woodall

Art Unit: 3733

Applicant respectfully submits that while Byrd does not disclose or suggest a plate mounted in free rotation in the bore of a nut at all, Blackburn fails to disclose or suggest a plate mounted completely within an open cylindrical inner part (bore) of the nut.

Blackburn discloses a cupped washer or bearing element 16 rotatably mounted over a boss 15, formed around an inner face of the nut. (see *Blackburn*; 1st col. of page 2, lines 45-50). However, referring especially to Blackburn's Figs. 2, 3, and 6, it can be seen that this washer 16 is not mounted within the bore of nut 13, but as Blackburn explains, is mounted over the boss 15, which is external to the bore of the nut 13.

Therefore, Byrd and Blackburn together fail to disclose or suggest a nut comprising a plate mounted completely within an open cylindrical inner part of the nut, the plate being in free rotation in and extending diametrically across the open cylindrical inner part.

Further, it is respectfully submitted that the references together fail to disclose or suggest two lateral clearances configured and dimensioned to receive, when the lateral branches of the fixing head are engaged in said lateral clearances, two pins of an auxiliary tool for gripping the nut in order to facilitate assembly of the nut on the fixing head.

As the examiner has recognized, Byrd does not disclose or suggest the plate mounted in free rotation in, and extending diametrically across, an open cylindrical inner part of the nut. Accordingly, Byrd cannot disclose or suggest that two lateral clearances are defined on either side of such a plate in order to allow passage of the branches of the fixing head inside the nut, and Byrd further cannot disclose or suggest that the two lateral clearances are configured to permit the insertion of two pins of an auxiliary tool for gripping the nut in order to facilitate assembly of the nut on the fixing head.

Blackburn also fails to disclose or suggest that two lateral clearances are defined on either side of such a plate in order to allow passage of the branches of the fixing head inside the nut, and that the two lateral clearances are configured and dimensioned to receive, when the lateral branches of the fixing head are engaged in the lateral

Application No.: 09/380,614

Examiner: N. W. Woodall

Art Unit: 3733

clearances, two pins of an auxiliary tool for gripping the nut in order to facilitate assembly

of the nut on the fixing head.

. . . .

Construing, arguendo, Blackburn's washer 16 and the rib 18 and brace 19 to

correspond to the claimed plate, there is no teaching or suggestion of two lateral

clearances configured to permit the insertion of two pins of an auxiliary tool for gripping

the nut in order to facilitate assembly of the nut on the fixing head, in addition to allowing

passage of the branches of the fixing head inside the nut.

On the contrary, referring to Blackburn's Figs. 5 and 10, it can be seen that the legs

2 and 3 of the keeper lug 1 entirely fill the spaces on either side of the rib 18 of the washer

16. There is no space provided for the insertion of any pins of an auxiliary tool for

gripping the nut in order to facilitate assembly of the nut onto the keeper lug 1.

Therefore, Blackburn cannot be construed to meet both of the elements of claim 1,

wherein the two lateral clearances accommodate, inside the nut together, both the branches

of the fixing head *and* two pins of an auxiliary tool for gripping the nut.

Not only does Blackburn not disclose or suggest that any lateral clearance is

configured to accommodate two pins of an auxiliary tool along with the branches of the

fixing head, Blackburn does not disclose or suggest any such auxiliary tool at all, or any

type of specialized tool for tightening the nut 13 onto the keeper lug 1.

Therefore, Blackburn lacks any teaching at all that would lead a person of ordinary

skill in the art to the presently claimed invention.

For at least these reasons, it is respectfully submitted that Byrd and Blackburn fail

to form a prima facie case of obviousness of the presently claimed invention. Therefore

claims 1 and 3-6 are allowable over the cited references, and withdrawal of the rejection is

requested.

Conclusion

In view of the amendments to the claims, and in further view of the foregoing

remarks, it is respectfully submitted that the application is in condition for allowance.

6

Application No.: 09/380,614

Examiner: N. W. Woodall

Art Unit: 3733

Accordingly, it is requested that claims 1 and 3-6 be allowed and the application be passed to issue.

If any issues remain that may be resolved by a telephone or facsimile communication with the Applicant's attorney, the Examiner is invited to contact the undersigned at the numbers shown.

Respectfully submitted,

BACON & THOMAS, PLLC 625 Slaters Lane, Fourth Floor Alexandria, Virginia 22314-1176 Phone: (703) 683-0500

Date: March 6, 2008

JOHN R. SCHAEFER Attorney for Applicant

Registration No. 47,921